



The part number for the replacement propeller is not printed correctly in the SPARE PARTS section of the Avistar Elite RTF manual on page 18.

The correct part number for the replacement propeller is GPMA4287.